


CYCLONE STRAP



• FOR CYCLONE STRAP LOOP AROUND CABLES


1. FIX BASE TO MOUNT SURFACE


• FOR CYCLONE STRAP START AT STEP 3


2. PLACE LINER AND CABLES ON BASE

3. WRAP AND CLIP LINER AS TIGHT AS POSSIBLE

4. FEED STRAP THOUGH BASE AND LOOP AROUND CABLES








SUGGESTED TORQUE 10 N/m

ACCESSORIES

C-clamp

Separation Pad





For use with un-slotted rungs.

Prevent galvanic corrosion between two dissimilar metals.

Contact CMP for more information regarding accessories and substrates.

PPE



CAUTION: We strongly recommend wearing suitable PPE including anti cut gloves.

Please refer to local PPE regulations.

Cable Cleat Specification								
Name	Туре	Base Material	Strap Material	Certification	Size Range	Temp Range	Liner Type	Bolt(s)*
I	LDSTR 2 LOOP	Aluminium	Stainless Steel	IEC 61914	O 36 - 118 mm in 8 sizes	-50°C to +40°C with LSF liner or -50°C to +90°C with HT liner	Low Smoke & Fume (LSF) & Phosphorus Free Polymer	2 x Outer M10 or
II	SDSTR 2 LOOP	Stainless Steel			24 - 145 mm in 15 sizes			
Ш	HDSTR 3 LOOP	Stainless Steel			21 - 68 mm in 8 sizes		VO Flame Retardant Polymer (HT)	M12

All products are short-circuit tested. Please visit www.cmp-products.com for further details.

Note: Fixings not included. For more information on fixings please visit www.cmp-products.com and download the Cleat Fixing Pack data sheet. Any other queries please contact CMP via email customerservices@cmp-products.com.


There are no restrictions on the mounting orientation of the cleats.

* The number of bolts used is based on individual site specification.

STRAP CABLE CLEATS

CYCLONE I LDSTR 2 LOOP CYCLONE II SDSTR 2 LOOP CYCLONE III HDSTR 3 LOOP

CYCLONE 2 STR INT RESTRAINT CYCLONE 3 STR INT RESTRAINT





Tel: +44 (0) 191 265 7411 Fax: +44 (0) 1670 715 646

E-mail: customerservices@cmp-products.com



GLOBAL

